



1

467128

041  8x	002  16x
004  10x	




The first callout shows a screw (002) being inserted into a hole in the metal. The second callout shows a washer (002) being placed over the screw head, with an arrow indicating the direction of rotation for tightening.



2


467128



617





4x






<p>125</p>  <p>8x</p>	<p>510</p>  <p>8x</p>
<p>004</p>  <p>8x</p>	<p>131</p>  <p>1x</p>



4

467128



125		4x	510		4x
001		3x	131		1x
004		2x	002		3x

